Avaya

7303 Exam

Avaya CallPilot(TM) Implementation Exam

https://www.certkillers.net

Question: 1

A technician is installing a 600r, and notices that the server boots to the Windows screen then starts booting again. It is stuck in a boot. What is the first step that should be taken?

A. Re-image the server.
B. Open a case requesting a replacement server.
C. Replace the hard drive.
D. Verify the SCSI terminator or tape drive is properly connected to the server.

Answer: B

Question: 2

A technician has completed the configuration and programming for an implementation of a new Avaya CallPilot system. When the Avaya CallPilot is rebooted, over which local Area Network (LAN) connection does the Communication Server 1000 communicate with the Avaya CallPilot voicemail system?

A. DSO
B. CLAN
C. ELAN
D. SLAN
E. TLAN

Answer: C

Question: 3

A company is planning to install a new Avaya CallPilot RIs. 5.0 system. They need a high availability system that will allow a standby server to lake over in case the primary server fails. Which hardware platform should be delivered on-site?

A. 703t
B. 600r
C. 1006r
D. 1002rp
E. 2250

Answer: C

Question: 4

A technician is installing an Avaya CallPilot with the NTRH40CA MBP96 CAT5 board and two

NTRB18DA Mgate cards. When cabling the NTRB18DA Mgate cards in a Communication Server 1000S Media Gateway, which statement describes the cabling configuration that is the most valid?

A**.** Attach the customer supplied RJ-45 cables to the face of the Mgate cards and then to the MBP96 card.
B**.** Attach the customer supplied RJ-45 cables to the backplane of the Media Gateway or Media Gateway expansion cabinet and then to the MBP96 card.
C**.** Attach NTDU0609 cables to the face of the Mgate cards and route them outside the Media Gateway. Then couple the customer supplied RJ-45 cables from the NTDU0609 to the MPB96 cards.
D**.** Attach the NTDU0609 cables to the face of the Mgate cards and take them outside the Media ay lo a customer supplied Ethernet hub. Attach RJ-45 cable from the hub to the MPB96 cards.

Answer: C

Question: 5

Which two additional software packages are installed during the Avaya CallPilot Reporter installation?

A**.** Adobo Acrobat
B**.** Crystal Repots
C**.** Application Builder
D**.** a Sybase database

Answer: B,D

Thank You for trying 7303 PDF Demo

To Buy Latest 7303 Full Version Download visit link below

https://www.certkillers.net/Exam/7303

Start Your 7303 Preparation

[Limited Time Offer] Use Coupon "CKNET" for Further discount on your purchase. Test your 7303 preparation with actual exam questions.