EMC

E20-340 Exam

CLARiiON Solutions Implementation

Thank you for Downloading E20-340 exam PDF Demo

You can also Buy our E20-340 Premium Full Version

https://www.certkillers.net/Exam/E20-340

https://www.certkillers.net

Question: 1

What do drives 0_0_0 to 0_0_4 in a CX4 contain?

A. FLARE and vault
B. Linux OS and metadata
C. DART and vault
D. Enginuity and metadata

Answer: A

Question: 2

What is a characteristic of disk-drive Spin Down?

A. Spin Down is only available on CX4.
B. Drives 0-4 are eligible for Spin Down.
C. Drive Spin Down is available for thin LUNs.
D. Drive Spin Down is available for all drives.

Answer: A

Question: 3

What is the maximum number of disk drives that can be configured in a pool on a CX4-480?

A. 475
B. 16
C. 480
D. 32

Answer: A

Question: 4

A customer currently has four CLARiiON arrays installed. They would like you to implement ESRS. What monitoring environment is a prerequisite for installing ESRS?

A. Centralized Monitoring
B. Distributed Monitoring
C. Storage Processor Email Monitoring
D. Host Based SNMP Monitoring

Answer: A

Question: 5

A customer would like to configure NTP using Unisphere. What is the minimum polling time allowed for NTP?

A. 30 minutes
B. 60 minutes
C. 15 minutes
D. 10 minutes

Answer: A

Question: 6

What communication protocol does Unisphere use?

A. SSL
B. SFTP
C. UDP
D. SSH

Answer: A

Question: 7

A customer has a CX4 series CLARiiON and is experiencing a problem with SPA . Upon arrival you notice that the SPA Fault LED is amber and flashing at a rate of four times a second. What is the boot state of SPA?

A. POST Starting OS
B. OS Booted
C. Executing BIOS
D. FLARE Driver Complete

Answer: A

Question: 8

Refer to the exhibit.

What is the correct order of the management module components?

A. A-GbE Service LAN; B-GbE Management LAN; C-Service Port COM1; D-SPS Port COM2; ENMI Button
B. A-GbE Management LAN; B-GbE Service LAN; C-Service Port COM1; D-SPS Port COM2; ENMI Button
C. A-SPS Port COM2; B-NMI Button; C-Service Port COM1; D-GbE Service LAN; E-GbE Management LAN
D. A-GbE Service LAN; B-GbE Management LAN; C-SPS Port COM2; D-Service Port COM1; EEMC NMI Button

Answer: A

Question: 9

Which statement accurately describes DAE3P enclosures?

A. Supported on CX3 and CX4 series arrays
B. Support the 2 Gb/s LCC card
C. Contain 14 disk drives
D. Support FC, ATA, Flash drives, and SATA-II drives

Answer: A

Question: 10

How many front-end ports are required to provide failover between SPs for eight direct-attached hosts on a CX4?

A. 16

B. 8
C. 4
D. 2

Answer: A

Question: 11

A customer has installed a new CX4 and is using ALUA SCSI communications with a Windows 2008 server and PowerPath. The server is using two LUNs on the array and they are both owned by SPA . Which statement describes how I/O is handled when a host has two paths to each SP, and there are no faults in this environment?

A. I/O will flow to the owning SP over the optimal paths.
B. I/O will flow to each SP and load balance all paths.
C. I/O will flow on only one path to each SP even if multiple paths are defined.
D. I/O flows to the owning SP and then will use the CMI bus for additional I/O.

Answer: A

Question: 12

What connectivity rules should be applied when configuring storage processor management ports on a CX4?

A. Both ports must be on the same subnet.
B. Both ports must be connected via CAT 5 cabling.
C. Both ports must be connected via 10/100 Ethernet.
D. Both ports must be directly connected to the host.

Answer: A

Thank You for trying E20-340 PDF Demo

To Buy our E20-340 Premium Full Version visit link below

https://www.certkillers.net/Exam/E20-340

Start Your E20-340 Preparation

""

Download and Pass Exam E20-340 Easily with CertKillers.net questions.