

## **IASSC**

## **ICBB Exam**

## IASSC Certified Lean Six Sigma Black Belt Exam

Thank you for Downloading ICBB exam PDF Demo

## You can Buy Latest ICBB Full Version Download

https://www.certkillers.net/Exam/ICBB

https://www.certkillers.net

#### Question: 1

A \_\_\_\_\_\_ is used primarily to track the stability of the average value of a metric of interest.

A. NP Chart B. Xbar-R Chart C. I-MR Chart

D. C Chart

Answer: B

#### Question: 2

For her injection molding project a Belt needed to track the percentage of defectives of a particular sample set so she used a \_\_\_\_\_\_ to display the data?

A. Individual Chart

- B. C Chart
- C. Xbar Chart
- D. P Chart

Answer: D

#### Question: 3

Which of these graphs demonstrates conditions which would be sufficient to enable OCAP for the process?

- A. Xbar Chart
- B. Time Series Chart
- C. Neither
- D. Both

Answer: A

#### **Question: 4**

Control Charts were developed by Dr. Shewhart to track data over time. To detect Special Cause variation the Control Charts use which of these?

- A. Data shift analysis
- B. Outlier analysis methods
- C. Center Line and Control Limits
- D. None of the above

## https://www.certkillers.net

Answer: C

#### **Question: 5**

Common and \_\_\_\_\_ Cause Variation are the focus of Statistical Process Control.

A. Uncommon

- B. Ordinary
- C. Special
- D. Selective

Answer: C

#### **Question: 6**

Special Cause Variation falls into which two categories?

A. Natural & Unnatural

B. Short Term & Long Term

C. Assignable & Pattern

D. Attribute & Discreet

Answer: C

#### Question: 7

Range Charts are the technique used to determine if Special Causes are occurring within the subgroups of the \_\_\_\_\_\_.

A. Histograms

- **B. SPC Charts**
- C. NP Charts
- D. Pareto Charts

Answer: B

#### **Question: 8**

If the production is for higher volume and monitoring and the Mean and variability is to be monitored for four machines producing product and the characteristic to be monitored is Variable Data, which SPC Chart is best to be selected?

- A. Xbar-R Chart
- B. Individual-MR Chart
- C. NP Chart
- D. CUSUM Chart

## https://www.certkillers.net

Answer: A

#### **Question: 9**

When a Belt Poka-Yoke's a defect out of the process entirely then she should track the activity with a robust SPC system on the characteristic of interest in the defect as an early warning system.

A. True B. False

Answer: B

#### **Question: 10**

Following the completion of a LSS project the Belt not only creates a Control Plan he also develops a \_\_\_\_\_\_ so those involved in the process know what to do when the critical metrics move out of spec.

A. Response Plan

B. Call List

C. Chain-of-Command

D. Defect Analysis Plan

Answer: A

## Thank You for trying ICBB PDF Demo

To Buy Latest ICBB Full Version Download visit link below

https://www.certkillers.net/Exam/ICBB

# **Start Your ICBB Preparation**

[Limited Time Offer] Use Coupon "CKNET" for Further discount on your purchase. Test your ICBB preparation with actual exam questions.